



RV Industry Hit With 65 Recalls

RV Manufacturers, Chassis Makers, RV Appliances and Suppliers Affected

Recalls as of November 7, 2016

The recalls noted below are not comprehensive for the recreational vehicle industry. They are merely a sampling of some of the known recalls currently in affect. Readers are encouraged to visit the National Highway and Safety Administration website at <http://www.nhtsa.gov/Vehicle+Safety/Recalls+&+Defects> to check on active recalls. Be sure to also check RV product vendors and your chassis manufacturer too. Sometimes recalls are chassis related and the recall may not appear as quickly for the manufacturers affected by the recall. All companies are listed alphabetically to more quickly assist you in locating your recall information. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

[Make a Service appointment](#) with Independence RV to have your recall repaired as soon as possible.

Cruiser RV (Cruiser) is recalling certain model year 2017 Shadow Cruiser, Fun Finder, MPG, Radiance, South Fork, and Stryker recreational trailers. The affected vehicles have an LED light on the front cap of the camper that may short circuit and overheat. If the light overheats there would be an increased risk of a fire.

Daimler Vans USA, LLC (DVUSA) is recalling certain model year 2016 Mercedes-Benz and Freightliner Sprinter 2500 and 3500 vehicles. The bolts connecting the lower seat belt connection to the rear bench seat may not have been properly tightened. Daimler Vans USA, LLC (DVUSA) is recalling certain model year 2016 Mercedes-Benz and Freightliner Sprinter 2500 and 3500 vehicles manufactured March 1, 2016, to May 31, 2016. The bolts connecting the lower seat belt connection to the rear bench seat may not have been properly tightened. If the

bolts were not properly tightened, the seat belt may fail to secure the seat occupant in the event of a crash.

Entegra Coach (Entegra) is recalling certain model year 2017 Cornerstone motorhomes. The affected vehicles have a power steering pump that may have an occasional loss of output power resulting in reduced or intermittent loss of power steering assist. Entegra Coach (Entegra) is recalling certain model year 2017 Cornerstone motorhomes manufactured April 13, 2016, to August 25, 2016. The affected vehicles have a power steering pump that may have an occasional loss of output power resulting in reduced or intermittent loss of power steering assist. An intermittent loss of power steering assist could increase the risk of a crash.

Ford Motor Company (Ford) is recalling certain model year 2016 E-350 and E-450 vehicles equipped with a 6.8L engine and an optional trailer brake controller. The trailer braking system may fail, increasing the distance needed to stop the vehicle. Ford Motor Company (Ford) is recalling certain model year 2016 E-350 and E-450 vehicles manufactured November 3, 2014, to December 10, 2015 and equipped with a 6.8L engine and an optional trailer brake controller. The trailer braking system may fail, increasing the distance needed to stop the vehicle. If the vehicle unexpectedly needs an extended braking distance, there would be an increased risk of a crash. Ford will notify owners, and dealers will reprogram the powertrain control module, free of charge. The recall began on February 19, 2016. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 16S01. Note: This recall supersedes 15V-710. Any vehicle previously repaired under 15V-710 will need to be repaired again.

Forest River, Inc. (Forest River) is recalling certain model year 2016-2017 Berkshire, and 2016 Coachmen Cross Country recreational vehicles and built on Daimler Trucks chassis. The front sway bar mounting brackets may not fit properly on the axle causing the mounting bolts to bend or loosen. Forest River, Inc. (Forest River) is recalling certain model year 2016-2017 Berkshire manufactured May 29, 2015, to April 26, 2016, and 2016 Coachmen Cross Country recreational vehicles manufactured April 30, 2015, to December 14, 2015 and built on Daimler Trucks chassis. The front sway bar mounting brackets may not fit properly on the axle causing the mounting bolts to bend or loosen. If the sway bar bolts loosen, the sway bar may detach from the axle, affecting the handling and increasing the risk of a crash. Forest River will notify owners, and Daimler Trucks dealers will modify the mounting of the sway bar, free of charge. The recall began on June 30, 2016. Owners may contact DTNA customer service at 1-800-547-0712. Forest River's number for this recall is 40-05032016-0183.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Cherokee recreational trailers, models CCKT16BHS, CCKT16FQ and CCKT17CJ,. The affected vehicles may have insufficient clearance between the bottom of the trailer and the top of the tire and, during use, the tire may make contact, possibly damaging the tire. Forest River, Inc. (Forest River) is recalling certain model year 2017 Cherokee recreational trailers, models CCKT16BHS, CCKT16FQ and CCKT17CJ, manufactured April 15, 2016, to July 28, 2016. The affected vehicles may have insufficient clearance between the bottom of the trailer and the top of the tire and, during use,

the tire may make contact, possibly damaging the tire. A damaged tire may unexpectedly deflate, causing a loss of vehicle control and increasing the risk of a crash.

Forest River, Inc. (Forest River) is recalling one model year 2015 XLR Hyperlite XLR31FDK recreational vehicle and equipped with a front deck for carrying motorcycles and quad runners and an optional fueling station. If the fueling station nozzle is fully extended and pulled as far forward as possible, the hose may be too close to the fuel burning appliance to prevent the fuel vapors from igniting. Forest River, Inc. (Forest River) is recalling one model year 2015 XLR Hyperlite XLR31FDK recreational vehicle manufactured September 30, 2014, to November 25, 2015, and equipped with a front deck for carrying motorcycles and quad runners and an optional fueling station. If the fueling station nozzle is fully extended and pulled as far forward as possible, the hose may be too close to the fuel burning appliance to prevent the fuel vapors from igniting. If the vapors released by fueling a vehicle stored in the trailer is able to reach the flame or heating element of a fuel burning appliance it may ignite, increasing the risk of a fire. The single unit affected by this campaign is still at the dealership and will be repaired by the dealer before delivery to the new owner. Therefore, an owner notification letter will not be issued for this campaign. The recall began on April 3, 2015. Owners may contact Forest River customer service at 1-574-642-0437. Forest River's number for this recall is 45-02172015.

Forest River, Inc. (Forest River) is recalling certain model year 2014-2015 Salem and Wildwood T174BH recreational vehicles. The affected vehicles may have an incorrect Gross Vehicle Weight Rating (GVWR) on the certification and tire information labels. As such, the vehicles do not conform to Part 567, "Certification." Forest River, Inc. (Forest River) is recalling certain model year 2014-2015 Salem and Wildwood T174BH recreational vehicles manufactured September 18, 2013, to August 29, 2014. The affected vehicles may have an incorrect Gross Vehicle Weight Rating (GVWR) on the certification and tire information labels. As such, the vehicles do not conform to Part 567, "Certification." If the trailer is loaded to the specifications listed on the label, tire failure may result, increasing the risk of a crash. Forest River will notify owners, and will provide corrected labels to the owners, free of charge. The recall began on November 11, 2014. Owners may contact Forest River customer service at 1-800-353-7383. Forest River's number for this recall is 2014-PLT6.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Salem and Wildwood recreational trailers. The Federal Placard on the affected vehicles incorrectly lists the tire and rim combination. The placard states ST225/75R15 Load Range C tires with an inflation pressure of 50PSI and a rim size of 15X6.0JJ, however, the trailer is equipped with ST225/75R15 Load Range D tires that have an inflation pressure of 65PSI, installed on 15X6.0JJ rims. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Forest River, Inc. (Forest River) is recalling certain model year 2017 Salem and Wildwood recreational trailers manufactured August 9, 2016, to September 6, 2016. The Federal Placard on the affected vehicles incorrectly lists the tire and rim combination. The placard states ST225/75R15 Load Range C tires with an inflation pressure of 50PSI and a rim size of 15X6.0JJ, however, the trailer is equipped with ST225/75R15 Load Range D tires that have an inflation pressure of 65PSI,

installed on 15X6.0JJ rims. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." The incorrect tire information on the Federal Label may result in the operator under-inflating the tires. An underinflated tire may cause sudden tire failure, or poor handling, increasing the risk of a crash.

Forest River, Inc. (Forest River) is recalling certain model year 2015-2017 Forester motorhomes, Sunseeker motorhomes, 2015-2016 Solera motorhomes, and 2016 Isata motorhomes. Water may leak into the electrical module that controls the vehicle taillights, brake lights, turn signal lights, clearance lights and marker lights, making the lights inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." Forest River, Inc. (Forest River) is recalling certain model year 2015-2017 Forester motorhomes manufactured June 10, 2014, to May 25, 2016, Sunseeker motorhomes manufactured April 4, 2014, to May 25, 2016, 2015-2016 Solera motorhomes manufactured February 28, 2014, to September 17, 2015, and 2016 Isata motorhomes manufactured October 30, 2015, to May 26, 2016. Water may leak into the electrical module that controls the vehicle taillights, brake lights, turn signal lights, clearance lights and marker lights, making the lights inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." If the rear brake lights fail to illuminate, following motorists may not realize that the vehicle in front of them is stopping. Inoperative taillights, clearance lights and marker lights will make the vehicle less visible to others. Either condition can increase the risk of a crash. The remedy for this recall is still under development. The recall is expected to begin August 18, 2016. Forester, Solera, and Sunseeker owners may contact Forest River customer service at 1-574-206-7600. Isata customers should call 1-574-262-3474. Forest River's number for this recall is 51-06012016-0206.

Forest River, Inc. (Forest River) is recalling certain model year 2015-2017 Forester motorhomes manufactured June 10, 2014, to May 25, 2016, Sunseeker motorhomes, and Solera motorhomes, and 2016 Isata motorhomes. Water may leak into the electrical module that controls the vehicle taillights, brake lights, turn signal lights, clearance lights and marker lights, making the lights inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." Forest River, Inc. (Forest River) is recalling certain model year 2015-2017 Forester motorhomes manufactured June 10, 2014, to May 25, 2016, Sunseeker motorhomes manufactured April 4, 2014, to May 25, 2016, 2015-2016 Solera motorhomes manufactured February 28, 2014, to September 17, 2015, and 2016 Isata motorhomes manufactured October 30, 2015, to May 26, 2016. Water may leak into the electrical module that controls the vehicle taillights, brake lights, turn signal lights, clearance lights and marker lights, making the lights inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment." If the rear brake lights fail to illuminate, following motorists may not realize that the vehicle in front of them is stopping. Inoperative

taillights, clearance lights and marker lights will make the vehicle less visible to others. Either condition can increase the risk of a crash.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Coachmen Freedom Express recreational vehicles, models FET28SE, FET282BHDS, FET282BHDSLE, FET281RLDS, FET281RLDSLE, FET29SE, FET292BHDS and FET292BHDSLE. These vehicles may have insufficient space between the slide room driveshaft and the driver's side tires, causing the tires to rub. Forest River, Inc. (Forest River) is recalling certain model year 2017 Coachmen Freedom Express recreational vehicles, models FET28SE, FET282BHDS, FET282BHDSLE, FET281RLDS, FET281RLDSLE, FET29SE, FET292BHDS and FET292BHDSLE, manufactured May 16, 2016, to July 19, 2016. These vehicles may have insufficient space between the slide room driveshaft and the driver's side tires, causing the tires to rub. If the driveshaft rubs against the tires, tire failure may result, possibly causing a loss of control and increasing the risk of a crash.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Rockwood and Flagstaff trailers. The affected vehicles are equipped with a Federal Placard that incorrectly indicates that the ST225/75R15D tires have a recommended pressure of 50 PSI. These tires should be maintained at 65PSI. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Forest River, Inc. (Forest River) is recalling certain model year 2017 Rockwood and Flagstaff trailers manufactured July 8, 2016, to July 11, 2016. The affected vehicles are equipped with a Federal Placard that incorrectly indicates that the ST225/75R15D tires have a recommended pressure of 50 PSI. These tires should be maintained at 65PSI. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." If the tires are run at a low pressure, they may overheat and fail, possibly causing a loss of vehicle control and increasing the risk of a crash.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Flagstaff and Rockwood trailers equipped with two air conditioners. There is may be excess slack in the wiring harness used in the air conditioner that contains a heating element. If the wires are not tied back and properly secured away from the heating element, the wires may contact the heating element, melt and short, increasing the risk of a fire.

Forest River, Inc. (Forest River) is recalling certain model year 2013-2017 Dynamax and Coachmen Pursuit recreational vehicles and 2016-2017 Freelanders and Orion recreational vehicles. The affected vehicles are equipped with shower curtains that may not adequately resist catching fire in the presence of an ignition source. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 302, "Flammability of Interior Materials." A flammable shower curtain may further fuel a fire, increasing the risk of injury.

Forest River, Inc. (Forest River) is recalling certain model year 2016-2017 Surveyor recreational vehicles, model ORSVT247BHDS. The Federal Placard installed on the vehicles

indicates an incorrect tire and rim combination. The Federal Placard states that the trailer is equipped with ST225/75R15D tires with 65 PSI and a rim designation of 15X6.0JJ, when actually they have ST205/75R14C tires with 50 PSI and a rim designation of 14X5.5JJ. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Forest River, Inc. (Forest River) is recalling certain model year 2016-2017 Surveyor recreational vehicles, model ORSVT247BHDS, manufactured August 10, 2016, to September 13, 2016. The Federal Placard installed on the vehicles indicates an incorrect tire and rim combination. The Federal Placard states that the trailer is equipped with ST225/75R15D tires with 65 PSI and a rim designation of 15X6.0JJ, when actually they have ST205/75R14C tires with 50 PSI and a rim designation of 14X5.5JJ. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." The operator may over-inflate the tire based on the information printed on the Federal Placard. Overinflating a tire may lead to pre-mature tire degradation, a tire blowout, or reduced handling, increasing the risk of a crash.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Surveyor recreational trailers, model SVT226RLDS. These vehicles may be equipped with tires and rims that do not match the information listed on the Federal Placard. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Forest River, Inc. (Forest River) is recalling certain model year 2017 Surveyor recreational trailers; model SVT226RLDS, manufactured October 9, 2015, to March 16, 2016. These vehicles may be equipped with tires and rims that do not match the information listed on the Federal Placard. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." The operator may over-inflate the tires based on the information printed on the Federal Placard, possibly resulting in sudden tire failure, causing a loss of vehicle control and increasing the risk of a crash.

Forest River, Inc. (Forest River) is recalling certain model year 2017 Coachmen Viking recreational trailers. The affected vehicles may be missing wire clip that retains the gas lift roof struts to the mounting bracket. Forest River, Inc. (Forest River) is recalling certain model year 2017 Coachmen Viking recreational trailers manufactured May 31, 2016, to August 23, 2016. The affected vehicles may be missing wire clip that retains the gas lift roof struts to the mounting bracket. Without the wire retaining clip, the roof lifting strut could detach from the mounting bracket, allowing one side of the roof to drop down quickly, increasing the risk of injury.

Daimler Trucks North America (DTNA) is recalling certain model year 2013-2016 Freightliner Custom Chassis Corporation (FCCC) XCM, XCR, and XCL motorhome chassis. On certain motorhome chassis built with a heavier, adjustable, straight foot pedal, the brake activation signal to certain towed devices may not deactivate when the motorhome service brakes are released. Daimler Trucks North America (DTNA) is recalling certain model year 2013-2016 Freightliner Custom Chassis Corporation (FCCC) XCM, XCR, and XCL motorhome chassis manufactured December 21, 2012, to December 22, 2015. On certain motorhome chassis built

with a heavier, adjustable, straight foot pedal, the brake activation signal to certain towed devices may not deactivate when the motorhome service brakes are released. If the brake activation signal to a towed device remains active when the motorhome chassis service brakes are released, the brakes on a towed device may remain engaged depending on brake configuration of the trailer. As a result, the brakes would drag and possibly overheat potentially resulting in a fire. Additionally, following drivers may be confused by the motorhome's actions, increasing the risk of a crash.

Daimler Vans USA, LLC (DVUSA) is recalling certain model year 2016 Mercedes-Benz and Freightliner Sprinter 2500 and 3500 vehicles. The bolts connecting the lower seat belt connection to the rear bench seat may not have been properly tightened. Daimler Vans USA, LLC (DVUSA) is recalling certain model year 2016 Mercedes-Benz and Freightliner Sprinter 2500 and 3500 vehicles manufactured March 1, 2016, to May 31, 2016. The bolts connecting the lower seat belt connection to the rear bench seat may not have been properly tightened. If the bolts were not properly tightened, the seat belt may fail to secure the seat occupant in the event of a crash.

Goodyear Tire & Rubber Company (Goodyear) is recalling certain G399A LHS tires, size 295/75R22.5 LRG. Due to an anomaly during the curing press set-up operation, incomplete adhesion between the tread and the top belt may have occurred. Goodyear Tire & Rubber Company (Goodyear) is recalling certain G399A LHS tires, size 295/75R22.5 LRG, manufactured January 24, 2016, to May 28, 2016. Due to an anomaly during the curing press set-up operation, incomplete adhesion between the tread and the top belt may have occurred. Incomplete adhesion may result in tread separation of the tire while in use, increasing the risk of a crash.

Grand Design RV, LLC (Grand Design) is recalling certain model year 2015-2017 Reflection recreational trailers, model 357BHS and 367BHS. The affected vehicles have an incorrect Gross Axle Weight Rating (GAWR) on the Federal Certification Label, stating a GAWR of 7,000 lbs. when the actual GAWR is 6,400 lbs. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification." Grand Design RV, LLC (Grand Design) is recalling certain model year 2015-2017 Reflection recreational trailers, model 357BHS and 367BHS, manufactured November 12, 2014, to September 22, 2016. The affected vehicles have an incorrect Gross Axle Weight Rating (GAWR) on the Federal Certification Label, stating a GAWR of 7,000 lbs. when the actual GAWR is 6,400 lbs. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification." If the operator loads the vehicle to the GAWR on the label, it can cause a loss of vehicle control, increasing the risk of a crash.

Heartland Recreational Vehicles, LLC (Heartland) is recalling certain model year 2016-2017 Wilderness and Mallard travel trailers, 2015-2017 Elkridge fifth wheel travel trailers, and 2017 Sundance and Torque travel trailers. The affected vehicles have an LED light on the front cap of the camper that may short circuit and overheat. If the light overheats there would be an increased risk of a fire.

Heartland Recreational Vehicles, LLC (Heartland) is recalling certain model year 2016-2017 Wilderness and Mallard travel trailers, 2015-2017 Elkridge fifth wheel travel trailers, and 2017 Sundance and Torque travel trailers. The affected vehicles have an LED light on the front cap of the camper that may short circuit and overheat. If the light overheats there would be an increased risk of a fire.

Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Flight trailers. The weight ratings on the tire labels are incorrect. Thus, these vehicles fail to comply with the requirements of Federal Vehicle Safety Standard (FMVSS) No. 110, "Tire Selection and Rims." Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Flight trailers manufactured May 6, 2016, to May 9, 2016. The weight ratings on the tire labels are incorrect. Thus, these vehicles fail to comply with the requirements of Federal Vehicle Safety Standard (FMVSS) No. 110, "Tire Selection and Rims." Incorrect weight ratings on the tire label could cause the operator to overload the vehicle and lead to premature tire wear, increasing the risk of a crash. All affected units are in dealer inventory. Dealers will be provided new, corrected labels. The recall began May 27, 2016. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is 9901299.

Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Flight SLX travel trailers, model 212 QBW. The affected vehicles were manufactured with Cargo Carrying Capacity (CCC) and Tire Labels indicating incorrect vehicle weight. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Flight SLX travel trailers; model 212 QBW, manufactured June 27, 2016, to June 28, 2016. The affected vehicles were manufactured with Cargo Carrying Capacity (CCC) and Tire Labels indicating incorrect vehicle weight. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Incorrect weight on labels can allow the operator to overload the vehicle, affecting vehicle handling, and increasing the risk of a crash. Jayco has notified the dealers that have the affected trailers and supplied them with corrected labels, free of charge. The recall began July 6, 2016. Owners may contact Jayco customer service at 1-800-2833-8267. Jayco's number for this recall is 9901300.

Jayco, Inc. (Jayco) is recalling certain model year 2016-2017 Jay Feather, Jay Flight, Jay Flight SLX, Eagle, White Hawk, and Octane travel trailers equipped with a Sway Command anti-sway system. When connected to certain tow vehicles that have an integrated brake controller, and after the anti-sway system has applied the trailer brakes in response to a sway event, the trailer brakes may no longer function to slow or stop the trailer. Jayco, Inc. (Jayco) is recalling certain model year 2016-2017 Jay Feather, Jay Flight, Jay Flight SLX, Eagle, White Hawk, and Octane travel trailers manufactured January 5, 2016, to July 18, 2016, equipped with a Sway Command anti-sway system. When connected to certain tow vehicles that have an integrated brake controller, and after the anti-sway system has applied the trailer brakes in response to a sway event, the trailer brakes may no longer function to slow or stop the trailer. A loss of trailer brakes may lengthen the distance needed to stop the vehicle and cause a loss of vehicle control, increasing the risk of a crash. Jayco will notify owners, and dealers will remove the

Sway Command system from the affected travel trailers, free of charge. The recall began on August 3, 2016. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is 9901308.

Jayco, Inc. (Jayco) is recalling certain model year 2013-2017 Redhawk motorhomes. The affected vehicles are equipped with shower curtains that may not adequately resist catching fire in the presence of an ignition source. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 302, "Flammability of Interior Materials." Jayco, Inc. (Jayco) is recalling certain model year 2013-2017 Redhawk motorhomes manufactured August 1, 2012, to June 24, 2016. The affected vehicles are equipped with shower curtains that may not adequately resist catching fire in the presence of an ignition source. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 302, "Flammability of Interior Materials." A flammable shower curtain may further fuel a fire, increasing the risk of injury.

Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Sport camping trailers equipped with the Baja Option. The inside walls of the tires on the affected vehicles may rub against the wheel wells, possibly resulting in a tire blowout. Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Sport camping trailers manufactured March 31, 2016, to September 30, 2016 and equipped with the Baja Option. The inside walls of the tires on the affected vehicles may rub against the wheel wells, possibly resulting in a tire blowout. Jayco, Inc. (Jayco) is recalling certain model year 2017 Jay Sport camping trailers manufactured March 31, 2016, to September 30, 2016 and equipped with the Baja Option. The inside walls of the tires on the affected vehicles may rub against the wheel wells, possibly resulting in a tire blowout. A tire blowout may increase the risk of a crash.

Jayco, Inc. (Jayco) is recalling certain 2017 Octane Super Lite travel trailers. The labels on the affected vehicles have incorrect tire load range and tire pressure information. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Jayco, Inc. (Jayco) is recalling certain 2017 Octane Super Lite travel trailers manufactured June 22, 2016, to June 23, 2016. The labels on the affected vehicles have incorrect tire load range and tire pressure information. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Incorrect tire pressure information may result in the tires being over inflated, which can cause their sudden failure, increasing the risk of a crash.

Jayco, Inc. (Jayco) is recalling certain model year 2016-2017 Alante and Precept motorhomes. The affected vehicles have a driver seat that may loosen and detach from the seat base as a result of the seat having been swiveled around. Jayco, Inc. (Jayco) is recalling certain model year 2016-2017 Alante and Precept motorhomes manufactured October 13, 2014, to June 23, 2016. The affected vehicles have a driver seat that may loosen and detach from the seat base as a result of the seat having been swiveled around. Jayco, Inc. (Jayco) is recalling certain model year 2016-2017 Alante and Precept motorhomes manufactured October 13, 2014, to

June 23, 2016. The affected vehicles have a driver seat that may loosen and detach from the seat base as a result of the seat having been swiveled around. If the seat detaches from the seat base while vehicle is being driven, the operator may lose control, increasing the risk of a crash.

Keystone RV Company (Keystone) is recalling certain model year 2011-2017 Bullet and Passport recreational trailers. The affected vehicles are equipped with an air conditioner LCD thermostat that may not be properly wired. If the thermostat is wired improperly, any damage to the thermostat wiring may result in an electrical short, increasing the risk of a fire.

Keystone RV Company (Keystone) is recalling certain model year 2017 Cougar recreational trailers, models CG28SGS17, CG28RDB17, CG28RKS17, CG29RES17, CG29RLI17 and CG28DBI17. The affected trailers have a Federal Identification Tag and Tire and Loading Information Label with incorrect information. Additionally, tires with the wrong load range may have been installed. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification." Keystone RV Company (Keystone) is recalling certain model year 2017 Cougar recreational trailers, models CG28SGS17, CG28RDB17, CG28RKS17, CG29RES17, CG29RLI17 and CG28DBI17, manufactured July 15, 2016, to August 3, 2016. The affected trailers have a Federal Identification Tag and Tire and Loading Information Label with incorrect information. Additionally, tires with the wrong load range may have been installed. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification." If tires of an incorrect load range are installed, tire failure may result, possibly causing a loss of vehicle control, and increasing the risk of a crash.

Keystone RV Company (Keystone) is recalling certain model year 2016-2017 Dutchmen Kodiak recreational. In the affected vehicles, the two sections of LED rope lights that serve as backlighting for the countertop each have exposed ends which may short against each other, possibly resulting in an electrical short. Keystone RV Company (Keystone) is recalling certain model year 2016-2017 Dutchmen Kodiak recreational trailers manufactured June 10, 2015 through April 6, 2016. In the affected vehicles, the two sections of LED rope lights that serve as backlighting for the countertop each have exposed ends which may short against each other, possibly resulting in an electrical short. An electrical short increases the risk of a fire. Keystone notified owners, and dealers will install a heat shrink tube over one of the LED rope light ends, free of charge. The recall began on June 8, 2016. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 16-255.

Keystone RV Company (Keystone) is recalling certain model year 2016-2017 Passport recreational trailers, model 3350BHWE. These trailers were built with axles that have a 3500 pound capacity instead of being built with axles that have a 4400 pound capacity. Keystone RV Company (Keystone) is recalling certain model year 2016-2017 Passport recreational trailers, model 3350BHWE, manufactured January 6, 2016, to April 21, 2016. These trailers were built with axles that have a 3500 pound capacity instead of being built with axles that have a 4400 pound capacity. If the vehicle is loaded to the specifications listed, the incorrect axle may be overloaded and fail as a result, increasing the risk of a crash. Keystone has notified owners, and dealers will replace the axle, free of charge. The recall began May 16, 2016. Owners may

contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 16-252.

Keystone RV Company (Keystone) is recalling certain model year 2013 Montana trailers, models 3100RL, 3150RL13, 3400RL, 3402RL, 3582RL, 3625RE, 3725RL, 3750FL, and 3900FB, and 2014 Mountaineer trailers, models 331RLT, 356TBF and 375FLF. In all models except the Mountaineer 375FLF, the rear windows are labeled with an exit sticker, but the rear window is not intended to be a secondary emergency exit. With the Mountaineer 375FLF, the rear window is intended as the secondary emergency exit, but it may be blocked by the rear ladder. Keystone RV Company (Keystone) is recalling certain model year 2013 Montana trailers, models 3100RL, 3150RL13, 3400RL, 3402RL, 3582RL, 3625RE, 3725RL, 3750FL, and 3900FB, manufactured November 12, 2012, to January 30, 2013, and 2014 Mountaineer trailers, models 331RLT, 356TBF and 375FLF, manufactured August 21, 2013, to September 18, 2013. In all models except the Mountaineer 375FLF, the rear windows are labeled with an exit sticker, but the rear window is not intended to be a secondary emergency exit. With the Mountaineer 375FLF, the rear window is intended as the secondary emergency exit, but it may be blocked by the rear ladder. In the event of an emergency, occupants could try to escape through the rear window, but would not be able to. This delay in their escape may increase the risk of injury. Keystone has notified owners, and dealers will remove the emergency exit sticker from the windows that were not intended to be emergency exits. Mountaineer 375FLF vehicles will have the window replaced, so that egress section of the window is on the opposite side of where the ladder is installed. These repairs will be performed free of charge. The recall began on July 9, 2015. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 15-232.

Keystone RV Company (Keystone) is recalling certain model year 2016-2017 Keystone Outback recreational trailers, model 326RL. These vehicles have a television mounting bracket that may not be properly secured to the wall. Keystone RV Company (Keystone) is recalling certain model year 2016-2017 Keystone Outback recreational trailers, model 326RL, manufactured February 24, 2016, to April 21, 2016. These vehicles have a television mounting bracket that may not be properly secured to the wall. The improperly secured bracket may allow the TV to fall, increasing the risk of injury to an occupant nearby. Keystone has notified the affected owners. Dealers will re-install the TV bracket with larger screws, free of charge. The recall began on May 13, 2016. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 16-251.

Keystone RV Company (Keystone) is recalling certain model year 2017 Dutchmen Coleman recreational trailers, models 1805RB, 3025RE, 2305QB, 3015BH, 262BH and 2605RL. Wiring in the power center may be loose and some wires may be frayed. Keystone RV Company (Keystone) is recalling certain model year 2017 Dutchmen Coleman recreational trailers, models 1805RB, 3025RE, 2305QB, 3015BH, 262BH and 2605RL, manufactured September 15, 2016, to September 27, 2016. Wiring in the power center may be loose and some wires may be frayed. Loose or frayed wiring may increase the risk of a fire.

Newmar Corporation (Newmar) is recalling certain model year 2017 Ventana, Ventana LE, and Dutch Star motorhomes built on a Freightliner Custom Chassis. In the affected vehicles, when the windshield wipers are turned off, the headlights may also turn off. Additionally, the wiper arms may stop in an incorrect location blocking the driver's view, and the wiper motor may stall when under load. Newmar Corporation (Newmar) is recalling certain model year 2017 Ventana, Ventana LE, and Dutch Star motorhomes manufactured November 1, 2015, to June 24, 2016 and built on a Freightliner Custom Chassis. In the affected vehicles, when the windshield wipers are turned off, the headlights may also turn off. Additionally, the wiper arms may stop in an incorrect location blocking the driver's view, and the wiper motor may stall when under load. If the headlights go out or the wiper system does not operate properly, the driver's visibility may be adversely affected, increasing the risk of a crash. Newmar will notify owners, and Freightliner dealers will update the wiper software, free of charge. The recall began on July 28, 2016. Owners may contact Newmar Customer Service Department at 1-800-731-8300.

Newmar Corporation (Newmar) is recalling certain model year 2017 Dutch Star, Mountain Aire, London Aire, Essex, and King Aire. The affected vehicles have front fascia wood trim that may separate from the slide out and possibly contact the driver or a passenger. Newmar Corporation (Newmar) is recalling certain model year 2017 Dutch Star, Mountain Aire, London Aire, Essex, and King Aire motorhomes manufactured December 4, 2015, to July 5, 2016. The affected vehicles have front fascia wood trim that may separate from the slide out and possibly contact the driver or a passenger. If the fascia separates and contacts the driver or a passenger, a loss of vehicle control may result, increasing the risk of a crash. Newmar will notify owners, and dealers will secure the trim with screws, free of charge. The recall is expected to begin September 3, 2016. Owners may contact Newmar customer service at 1-800-731-8300.

Newmar Corporation (Newmar) is recalling certain model year 2014-2016 Dutch Star motorhomes built on a Freightliner chassis. In the affected vehicles, the steering box may have been manufactured with an incorrect spacer with insufficient height that can cause too much play, causing the connection to wear between the steering wheel and the front axle. Newmar Corporation (Newmar) is recalling certain model year 2014-2016 Dutch Star motorhomes manufactured from June 5, 2014, through October 16, 2015, and built on a Freightliner chassis. In the affected vehicles, the steering box may have been manufactured with an incorrect spacer with insufficient height that can cause too much play, causing the connection to wear between the steering wheel and the front axle. The steering wheel's connection to the front axle could fail resulting in a sudden loss of steering control, increasing the risk of a crash. Newmar will notify owners, and Freightliner dealers will inspect and replace the steering box if necessary, free of charge. Note: Owners are urged not to drive their vehicles until they have been inspected. The recall began on July 14, 2016. Owners may contact Freightliner customer service at 1-800-547-0712 or Newmar customer service at 1-800-731-8300. Newmar's number for this recall is 16V 366.

Newmar Corporation (Newmar) is recalling certain model year 2014-2016 Dutch Star and Mountain Aire and 2015-2016 London Aire and Essex motorhomes built on a Freightliner (Daimler Trucks North America) chassis. The throttle pedal position sensor on the affected vehicles may not return to zero, causing the engine brake to suddenly not activate as expected, reducing the vehicle's deceleration ability. Newmar Corporation (Newmar) is recalling certain model year 2014-2016 Dutch Star and Mountain Aire and 2015-2016 London Aire and Essex motorhomes built on a Freightliner (Daimler Trucks North America) chassis. The throttle pedal position sensor on the affected vehicles may not return to zero, causing the engine brake to suddenly not activate as expected, reducing the vehicle's deceleration ability. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity, potentially increasing the risk of a crash. Newmar will notify owners, and DTNA dealers will replace the throttle pedal, free of charge. The recall began on August 5, 2016. Owners may contact Newmar Customer Service Department at 1-800-731-8300 or Daimler Trucks North America LLC at 1-800-547-0712, or by e-mail at DTNA.Warranty.Campaigns@Daimler.com. Newmar's number for this recall is 16V 321.

Newmar Corporation (Newmar) is recalling certain model year 2015 Dutch Star motorhomes built on a Freightliner Custom Chassis Corporation (FCCC) XCM, XCR, or XCL motorhome chassis. In these vehicles with a heavier, adjustable, straight foot pedal, the brake activation signal to certain towed devices may not deactivate when the motorhome service brakes are released. Newmar Corporation (Newmar) is recalling certain model year 2015 Dutch Star motorhomes manufactured July 24, 2014, to September 10, 2014 and built on a Freightliner Custom Chassis Corporation (FCCC) XCM, XCR, or XCL motorhome chassis. In these vehicles with a heavier, adjustable, straight foot pedal, the brake activation signal to certain towed devices may not deactivate when the motorhome service brakes are released. If the brake activation signal to a towed device remains active when the motorhome chassis service brakes are released, the brakes on a towed device may remain engaged depending on brake configuration of the trailer. As a result, the brakes would drag and possibly overheat potentially resulting in a fire. Additionally, following drivers may be confused by the motorhome's actions, increasing the risk of a crash.

Newmar Corporation (Newmar) is recalling certain model year 2014-2016 Dutch Star and Mountain Aire and 2015-2016 London Aire and Essex motorhomes built on a Daimler Trucks North America (DTNA) chassis. The throttle pedal position sensor on the affected vehicles may not return to zero, causing the engine brake to suddenly not activate as expected, reducing the vehicle's deceleration ability. Newmar Corporation (Newmar) is recalling certain model year 2014-2016 Dutch Star and Mountain Aire and 2015-2016 London Aire and Essex motorhomes manufactured January 28, 2013, to December 14, 2015 and built on a Daimler Trucks North America (DTNA) chassis. The throttle pedal position sensor on the affected vehicles may not return to zero, causing the engine brake to suddenly not activate as expected, reducing the vehicle's deceleration ability. A sudden loss of an engine brake without warning on a motorhome may lead to a reduced brake capacity, potentially increasing the risk of a crash.

Newmar Corporation (Newmar) is recalling certain model year 2015-2017 Canyon Star recreational vehicles. These vehicles have a wheelchair access door with a power door lock that may open while the vehicle is in motion if the key fob button is pressed accidentally.

Newmar Corporation (Newmar) is recalling certain model year 2015-2017 Canyon Star recreational vehicles manufactured June 5, 2014, to September 6, 2016. These vehicles have a wheelchair access door with a power door lock that may open while the vehicle is in motion if the key fob button is pressed accidentally. If the wheelchair access door opens while the vehicle is being driven, it could cause a loss of vehicle control, increasing the risk of a crash.

Newmar Corporation (Newmar) is recalling certain model year 2012-2017 Canyon Star motor homes and equipped with wheelchair lifts. Incorrect bolts may have been used to install the wheelchair lift base. These bolts may unexpectedly break allowing the lift to move. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 404, "Platform Lift Installations." Newmar Corporation (Newmar) is recalling certain model year 2012-2017 Canyon Star motor homes manufactured September 7, 2011, to September 6, 2016 and equipped with wheelchair lifts. Incorrect bolts may have been used to install the wheelchair lift base. These bolts may unexpectedly break allowing the lift to move. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 404, "Platform Lift Installations." Unintentional movement of the wheelchair lift can cause injury to the lift occupant and/or the lift operator.

Newmar Corporation (Newmar) is recalling certain model year 2017 King Aire motorhomes. The affected vehicles are equipped with WABCO OnGuard collision mitigation radar which may have been mounted upside down on the front lower bumper, resulting in decreased performance. Newmar Corporation (Newmar) is recalling certain model year 2017 King Aire motorhomes manufactured January 22, 2016, to October 4, 2016. The affected vehicles are equipped with WABCO OnGuard collision mitigation radar which may have been mounted upside down on the front lower bumper, resulting in decreased performance. If the collision mitigation radar has reduced performance, there may be an increased risk of a crash.

Newmar Corporation (Newmar) is recalling certain model year 2017 Newmar King Aire, Essex, London Aire, and Mountain Aire motorhomes built on a Spartan Motors chassis. The affected vehicles have a power steering pump that may have an occasional loss of output power resulting in reduced or intermittent loss of power steering assist. Newmar Corporation (Newmar) is recalling certain model year 2017 Newmar King Aire, Essex, London Aire, and Mountain Aire motorhomes manufactured May 12, 2016, to August 23, 2016 and built on a Spartan Motors chassis. The affected vehicles have a power steering pump that may have an occasional loss of output power resulting in reduced or intermittent loss of power steering assist. An intermittent loss of power steering assist could increase the risk of a crash.

Outdoors RV Manufacturing (ORV) is recalling certain model year 2015-2017 Glacier Peak fifth-wheel travel trailers. The affected trailers have a pin box that may flex resulting in metal fatigue and possibly the separation of the fifth-wheel trailer from the tow vehicle. If the fifth-wheel separates from the tow vehicle there would be an increased risk of a crash.

Discount Tire is recalling certain Pathfinder SAT LT245/75R17E1 121R W tires, Pathfinder SAT LT265/75R16E1 123Q W tires, Pathfinder SAT LT265/70R17E1 121S B, and Pathfinder SAT LT275/65R18E1 123S B tires. These replacement light truck tires may have been manufactured with an inner liner gauge that is lower than specified. As a result, the tire tread may separate and cause rapid air pressure loss. Discount Tire is recalling certain Pathfinder SAT LT245/75R17E1 121R W tires manufactured September 16, 2013, to May 19, 2015, Pathfinder SAT LT265/75R16E1 123Q W tires manufactured August 5, 2013, to May 19, 2015, Pathfinder SAT LT265/70R17E1 121S B tires manufactured September 2, 2013, to May 19, 2015, and Pathfinder SAT LT275/65R18E1 123S B tires manufactured October 7, 2013, to May 19, 2015. These replacement light truck tires may have been manufactured with an inner liner gauge that is lower than specified. As a result, the tire tread may separate and cause rapid air pressure loss. If a tire experiences tread separation or air pressure loss, it can increase the risk of a vehicle crash. Discount Tire will notify owners, and dealers will provide replacement tires or refund the purchase price, free of charge. The recall began on August 21, 2015. Owners may contact Discount Tire customer service at 1-888-519-6914.

Pleasant Valley Teardrop Trailers LLC (Pleasant Valley) is recalling certain model year 2013-2017 T@B travel trailers equipped with a 3-way refrigerator. The affected vehicles have a rubber gas hose in the refrigerator compartment that can rub against the refrigerator fins, causing the hose to wear and possibly leak propane. Pleasant Valley Teardrop Trailers LLC (Pleasant Valley) is recalling certain model year 2013-2017 T@B travel trailers manufactured January 1, 2013 through August 31, 2016 and equipped with a 3-way refrigerator. The affected vehicles have a rubber gas hose in the refrigerator compartment that can rub against the refrigerator fins, causing the hose to wear and possibly leak propane. A propane leak increases the risk of a fire.

Shower Enclosures America, Inc. (SEA) is recalling certain Arcadia shower curtains. These shower curtains may not adequately resist catching fire in the presence of an ignition source. As such, these curtains fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 302, "Flammability of Interior Materials." Shower Enclosures America, Inc. (SEA) is recalling certain Arcadia shower curtains manufactured February 1, 2012, to July 15, 2016. These shower curtains may not adequately resist catching fire in the presence of an ignition source. As such, these curtains fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 302, "Flammability of Interior Materials." A flammable shower curtain may further fuel a fire, increasing the risk of injury.

Spartan Motors, Inc. (Spartan) is recalling certain model year 2015 K3 Chassis. The steering slip shaft, located between the steering column and steering gear, may prematurely wear. Spartan Motors, Inc. (Spartan) is recalling certain model year 2015 K3 Chassis manufactured November 22, 2013, to October 28, 2014. The steering slip shaft, located between the steering column and steering gear, may prematurely wear. Premature wear of the steering slip shaft may increase the risk of a vehicle crash. Spartan will notify owners, and dealers will replace the

affected slip shaft, free of charge. The recall began on February 3, 2015. Owners may contact Spartan customer service at 1-517-543-6400. Spartan's number for this recall is 14022.

Starcraft RV (Starcraft) is recalling certain model year 2016 Travel Star travel trailers, models G2JB5099-5101, JD5093-5094, JF5079, JG5067, and JN5065-5066; and Launch Ultra Lite travel trailers, models G2JM5112-5113, JR5187-5197, JS5179-5196, JT5533-5639, JU5121-5155, and JZ5128-5160. In the affected trailers, the water heater may be improperly wired such that the warning light will not illuminate to let the operator know that the gas is on but did not ignite. Starcraft RV (Starcraft) is recalling certain model year 2016 Travel Star travel trailers, models G2JB5099-5101, JD5093-5094, JF5079, JG5067, and JN5065-5066; and Launch Ultra Lite travel trailers, models G2JM5112-5113, JR5187-5197, JS5179-5196, JT5533-5639, JU5121-5155, and JZ5128-5160, manufactured from August 7, 2015, through October 6, 2015. In the affected trailers, the water heater may be improperly wired such that the warning light will not illuminate to let the operator know that the gas is on but did not ignite. If the warning light does not illuminate to notify the operator that the gas did not ignite, a buildup of gas may result, increasing the risk of fire in the presence of an ignition source. Starcraft will notify owners, and dealers will correct the water heater wiring, free of charge. The recall began on November 30, 2015. Owners may contact Starcraft customer service at 1-800-945-4787. Starcraft's number for this recall is 9902261.

Starcraft RV (Starcraft) is recalling certain model year 2016-2017 AR-ONE Maxx travel trailers and fifth wheels. The affected vehicles may be equipped with a Federal Label with incorrect tire information, and as a result, the owner could replace the tire with an incorrect size. As such, these vehicles fail to comply with the Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." Starcraft RV (Starcraft) is recalling certain model year 2016-2017 AR-ONE Maxx travel trailers and fifth wheels manufactured May 4, 2015, to June 27, 2016. The affected vehicles may be equipped with a Federal Label with incorrect tire information, and as a result, the owner could replace the tire with an incorrect size. As such, these vehicles fail to comply with the Federal Motor Vehicle Safety Standard (FMVSS) number 110, "Tire Selection and Rims." If the tire is replaced with an incorrect tire size, vehicle handling could be affected, increasing the risk of a crash. Starcraft will notify owners, and dealers will install a corrected Federal and Tire label, free of charge. The recall began on August 5, 2016. Owners may contact Starcraft customer service at 1-800-945-4787. Starcraft's number for this recall is 9902307.

Thor Motor Coach (Thor) is recalling certain model year 2012-2017 Ace, 2013 Citation, 2012-2013 Siesta and 2017 Four Winds and Road Bear Rental motorhomes. The affected vehicles are equipped with shower curtains that may not adequately resist catching fire in the presence of an ignition source. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 302, "Flammability of Interior Materials." A flammable shower curtain may further fuel a fire, increasing the risk of injury.

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2007-2011 Allegro, Allegro Bus, Phaeton, and Zephyr motorhomes, 2007-2010 Allegro Bay motorhomes, and 2010-2011

Allegro Breeze motorhomes. The windshield wiper arms on the affected vehicles may break off. Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2007-2011 Allegro, Allegro Bus, Phaeton, and Zephyr motorhomes, 2007-2010 Allegro Bay motorhomes, and 2010-2011 Allegro Breeze motorhomes. The windshield wiper arms on the affected vehicles may break off. If the windshield wiper arms break, the driver's visibility may be reduced, increasing the risk of a crash. Tiffin will notify owners, and dealers will replace the wiper blade arms, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Tiffin customer service at 1-256-356-8661. Tiffin's number for this recall is TIFF-100.

Tiffin Motorhomes (Tiffin) is recalling certain model year 2017 Allegro Open Roads vehicles. The affected vehicles have a driver-side wiper arm that may sweep off of the edge of the windshield, when trying to return, the wiper arm may break. Tiffin Motorhomes (Tiffin) is recalling certain model year 2017 Allegro Open Roads vehicles manufactured June 7, 2016, to August 15, 2016. The affected vehicles have a driver-side wiper arm that may sweep off of the edge of the windshield, when trying to return, the wiper arm may break. Tiffin Motorhomes (Tiffin) is recalling certain model year 2017 Allegro Open Roads vehicles manufactured June 7, 2016, to August 15, 2016. The affected vehicles have a driver-side wiper arm that may sweep off of the edge of the windshield, when trying to return, the wiper arm may break. A broken windshield wiper may reduce the driver's visibility, increasing the risk of a crash.

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2016-2017 Breeze motorhomes. The affected vehicles have air compressors attached to the engine that may fail due to debris from manufacturing being left in the air intake tube. Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2016-2017 Breeze motorhomes manufactured July 7, 2015, to June 14, 2016. The affected vehicles have air compressors attached to the engine that may fail due to debris from manufacturing being left in the air intake tube. Failure of the air compressor may result in the inability to maintain air pressure while driving which would cause the parking brake to set unexpectedly, increasing the risk of a crash.

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2015-2017 Allegro motorhomes. The affected vehicles have a tow hitch with a weight capacity sticker that may indicate an incorrect weight capacity. Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2015-2017 Allegro motorhomes manufactured April 1, 2015, to September 16, 2016. The affected vehicles have a tow hitch with a weight capacity sticker that may indicate an incorrect weight capacity. If the hitch is loaded to the weight on sticker, the hitch may fail and the towed vehicle can separate from the motorhome, increasing the risk of a crash.

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2017 Allegro Bus motorhomes. Due to insufficient holding power of the mirror arm swivel mechanism, the passenger side mirror could move while the vehicle is in motion. Tiffin Motorhomes, Inc. (Tiffin) is recalling certain model year 2017 Allegro Bus motorhomes manufactured April 12, 2016, to June 21, 2016. Due to insufficient holding power of the mirror arm swivel mechanism, the passenger side mirror could move while the vehicle is in motion. If the mirror does not stay in position, it can reduce the driver's visibility, increasing the risk of a crash.

Triple E Recreational Vehicles (Triple E) is recalling certain model year 2016 Unity motorhomes, model U24X. The affected vehicles have a showerhead that can be lowered into the shower pan or sink basin. Triple E Recreational Vehicles (Triple E) is recalling certain model year 2016 Unity motorhomes; model U24X, manufactured October 15, 2015, to June 16, 2016. The affected vehicles have a showerhead that can be lowered into the shower pan or sink basin. In the event of a waste water backup, a submerged showerhead may syphon the waste water, possibly contaminating the fresh water supply, increasing the risk of injury.

Triple E Recreational Vehicles (Triple E) is recalling certain model year 2016-2017 Unity recreational vehicles, models U24TB and U24IB. The Truma propane water heater line on the affected vehicles may be damaged from items moving within the lower storage compartment, causing the line to rupture and allow propane gas to leak out. Triple E Recreational Vehicles (Triple E) is recalling certain model year 2016-2017 Unity recreational vehicles, models U24TB and U24IB, manufactured March 1, 2016, to June 9, 2016. The Truma propane water heater line on the affected vehicles may be damaged from items moving within the lower storage compartment, causing the line to rupture and allow propane gas to leak out. A propane gas leak in the presence of an ignition source increases the risk of a fire. Triple E will notify owners, and dealers will reposition the protective cleat for the gas line, free of charge. The recall began on August 15, 2016. Owners may contact Triple E customer service at 1-877-992-9906. Triple E's number for this recall is CA#8349-1.

Universal Trailer Cargo Group, Inc. (Universal Trailer) is recalling certain model year 2007-2010 Haulmark Motorcoach vehicles. The bolt that attaches the fan gear assembly to the steps may fracture allowing the fan gear to disengage from the steps. As a result, the steps may not remain in the expected position and may become unstable. Universal Trailer Cargo Group, Inc. (Universal Trailer) is recalling certain model year 2007-2010 Haulmark Motorcoach vehicles manufactured April 1, 2007, to June 30, 2010. The bolt that attaches the fan gear assembly to the steps may fracture allowing the fan gear to disengage from the steps. As a result, the steps may not remain in the expected position and may become unstable. Unstable entry and exit steps increase the risk of injury. Universal Trailer will notify owners, and dealers will install a retainer bracket on the double step assemblies and the Coachstep Linkage Assembly will be replaced and a retainer bracket will be installed on the trip step assemblies. The recall began on May 2, 2016. Owners may contact Universal Trailer customer service at 1-574-264-9661.

Winnebago Industries, Inc. (Winnebago) is recalling certain model year 2015-2017 Itasca Cambria, 2015-2017 Winnebago ERA, Travato, Fuse, Aspect, and Vista recreational vehicles, and 2015-2017 Itasca Sunstar recreational vehicles. The affected vehicles may have an electrical connection to the automatic transfer switch (ATS) that may not be properly tightened. Winnebago Industries, Inc. (Winnebago) is recalling certain model year 2015-2017 Itasca Cambria, 2015-2017 Winnebago ERA, Travato, Fuse, Aspect, and Vista recreational vehicles, and 2015-2017 Itasca Sunstar recreational vehicles manufactured May 6, 2014, to April 22, 2016. The affected vehicles may have an electrical connection to the automatic

transfer switch (ATS) that may not be properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of a fire.

Winnebago Towable (Winnebago) is recalling certain model year 2016-2017 Winnebago Winnie Drop, Micro Minnie, Minnie, Minnie Plus, Spyder, Scorpion, Destination, Instinct, and Voyage travel trailers. The weight label on the affected vehicles incorrectly states the fresh water capacity in gallons when it should be stated in pounds. Winnebago Towable (Winnebago) is recalling certain model year 2016-2017 Winnebago Winnie Drop, Micro Minnie, Minnie, Minnie Plus, Spyder, Scorpion, Destination, Instinct, and Voyage travel trailers manufactured November 9, 2015, to September 6, 2016. The weight label on the affected vehicles incorrectly states the fresh water capacity in gallons when it should be stated in pounds. The incorrect information may cause the trailer to be overloaded, possibly resulting in a loss of control and increasing the risk of a crash.

SOURCE: NHTSA's Office of Defects Investigation

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1.888.327.4236 or go to www.safercar.gov for further inquiries.

[Make a Service appointment](#) with Independence RV to have your recall repaired as soon as possible.